



Plate 7: Close up of fissure.



Plate 8: Plastic piping and recent scars on Graig-y-Merched roadway indicate ongoing movement and repairs.

PROJECT: PANTTEG LANDSLIDE

PLATES



EARTH SCIENCE PARTNERSHIP

33 Cardiff Road, Taffs Well, Cardiff CF15 7RB

Tel: 029 2081 3385 enquiries@earthsciencepartnership.com